



Refer to clutch roller replacement instructions in the service manual for your CAN-AM UTV

Specific to HI-TORQUE ROLLERS Part #DBP-CA-X3-300:

- If there is any roughness on the stud rolling surface, polish the pin using 400 grit or finer abrasive paper until smooth.
- Replace the pin, passing it through the washer first and then the roller, with the **shiny face that has our logo** against the washer.